Work Order ID 96715  Monday, February 11, 2013 4:24:39 PM						Page 1							
Item ID: Revision ID: Item Name:	D3849-041 Fwd Wearplate Assembly, STD Gear		iear		Accept	*N900040100			)* s	Setup Star	1 1	S1* S2*	
Start Date: Required Date Reference:		Start Qty: 1.0  Req'd Qty: 1.0  416 - 227	0	*1* *1*		Cust Item II Customer:		AR001					
Approvals:	Process Plan: MF QC:			13-2-11		Date:		·	F	Run Stai Sto	" <b>[V</b> ]	R1* R2*	
Sequence ID/ Work Center I	D	Operation Description			Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
Draw Nbr	Revi	ision Nbr											
D3849	D												
*100 *100* QC Quality Control		D3849	CT RA 111416 041 X 1 B#530 PLATE IS SCR		0.00 0.00 16 1.80	(z) 12							
*110 *110* Small Fab Small Fab		<b>Memo</b> SCRAI	<b>)</b>		0.00				()	<b>_</b>	_Æ	13.02.12	
120 *120* QC		QC21- Final Inspec	tion - Work Ord	er Release	0.00					131	2/20	0	

Quality Control

MLJ 13-02-12

Page 1

Work Order ID:

96715

Monday, February 11, 2013 4:24:39 PM

Parent Item:

D3849-041

Parent Item Name:

Fwd Wearplate Assembly, STD Gear

Start Date: 1/31/2013

Required Date: 2/1/2013

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP RevA: New issue DD verified by:EC

DWG REV.D DD VERF:JLM

IPP Rev:B 12.09.11 AS PER

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3849-041		Manufactured	No				Each	6.0000		1		····	
Fwd Wearplate Assembly,	STD Gear												4/8 <b>a</b> /
				Location		Loc Oty	<u>L</u>	oc Code					
				FP-001		2							
				931	52	2							
				FP002		4							

90319

( x53036 mf